BRM
LAND AFRICA

ALERT BRM-01/2026

OCTOBER 07, 2026

Subject: Closing the fuel valve

Applicability – Land Africa, all.

Okavango, all.

Possible accidental closure of the fuel valve caused by floor mat movement.

BRM Construções Aeronáuticas hereby informs all its representatives, resellers, and owners that one of the following corrective actions is MANDATORY.

Corrective actions:

1 – Floor mat removal:

2 – Secure the mat to the floor.

Mimosas - Montelavar Apartado 8
2715-952 PERO PINHEIRO
PORTUGAL
Telefone: 21 967 81 39
~~Fax: 21~~ 927 12 45
E-mail: mvistas@vrv.pt
Contribuinte Nº 506 585 816

BRM CONSTRUÇÕES AERONÁUTICAS